

## General Information

Date & Time: 29, Oct, 2024 13:04

<b>Make</b>	Toyota	<b>Model</b>	Veloz
<b>YOM</b>	2024	<b>Mileage</b>	7,286
<b>Registration No.</b>	EAJ1247	<b>Chassis No.</b>	MHFAB1BY3P3069284
<b>CC</b>	1.5	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Purple		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	118	111	119
2	Boot Lid	111.0	111	119	103
3	Roof	129.5	135	139	120/124
4	Left Front Fender	114.0	113	120	109
5	Left Front Door	118.0	111	120	123
6	Center Panel Left				
7	Left Rear Door	134.6	119	117	168
8	Left Back Panel	136.3	145	125	139
9	Right Front Fender	108.3	108	110	107
10	Right Front Door	120.3	134	114	113
11	Center Panel Right				
12	Right Rear Door	124.3	128	119	126
13	Right Back Panel	132.0	116	132	148

Overall Evaluation :

**A**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Dashboard - Traces of Adhesive Tape - Yes</p>	<p><b>Remarks</b> (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Rear Door, Molding - Scratch - Large / Roof - Dent - Small</p>
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Defects not found</p>

<p><b>Inspector Notes</b></p>
<p>swirl marks and hairline scratches present/ good condition</p>