


General Information

Date & Time: 01, Jul, 2025 14:42

Make	Suzuki	Model	APV
YOM	2024	Odo Meter Reading	15,305
Registration No.	NKD6333	Chassis No.	MHYDN71V6RJ402162
CC	1.6	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	117	119	111
2	Boot Lid	117.3	109	130	113
3	Roof	98.0	90	85	114/103
4	Left Front Fender	108.3	95	112	118
5	Left Front Door	131.0	134	127	132
6	Center Panel Left	112.3	114	116	107
7	Left Rear Door	130.6	129	129	134
8	Left Back Panel	123.0	126	113	130
9	Right Front Fender	119.6	110	115	134
10	Right Front Door	126.3	137	124	118
11	Center Panel Right	123.6	116	129	126
12	Right Rear Door	133.3	134	132	134
13	Right Back Panel	122.6	121	116	131

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small	Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Roof - Scratch - Minimal / Front Panel - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with LTO plate, with warranty booklet, with jack and tools, with spare tire
