


General Information

Date & Time: 24, Jun, 2025 11:45

Make	Toyota	Model	Lite Ace
YOM	2022	Odo Meter Reading	34,456
Registration No.	NID6570	Chassis No.	MHKU3FE10NK000545
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	53.9	51	57	54
2	Boot Lid	49.8	50	50	50
3	Roof	46.8	46	51	44/47
4	Left Front Fender	49.8	53	45	52
5	Left Front Door	51.9	52	49	55
6	Center Panel Left	76.0	81	59	89
7	Left Rear Door				
8	Left Back Panel	45.7	46	46	45
9	Right Front Fender	60.9	63	66	54
10	Right Front Door	48.9	47	52	48
11	Center Panel Right	61.9	66	52	68
12	Right Rear Door				
13	Right Back Panel	44.2	43	48	42

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / (R) Front Trim - Grime - Medium	Remarks (R) Side Gate - Rust, Corrosion - Large / (L) Side Gate - Rust, Corrosion - Large / Cargo Bed Floor - Rust, Corrosion - Large / (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / Rear Gate - Rust, Corrosion - Large / Cab Back Panel - Rust, Corrosion - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Medium / (L) Center Panel - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Panel - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Rust, Corrosion - Large / Rear Bumper, Lamps, Panels - Modified - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, no jack, with tools, with spare tire, with LTO plate