

General Information

Date & Time: 27, Jun, 2025 15:41

Make	Toyota	Model	Avanza
YOM	2024	Odo Meter Reading	3,735
Registration No.	DBM4540	Chassis No.	MHFAA1BY3R0023817
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	104	111	113
2	Boot Lid	99.0	94	105	98
3	Roof	124.0	127	132	113/124
4	Left Front Fender	99.4	99	99	101
5	Left Front Door	113.0	111	108	120
6	Center Panel Left				
7	Left Rear Door	115.0	119	108	118
8	Left Back Panel	119.3	121	100	137
9	Right Front Fender	106.0	112	108	98
10	Right Front Door	115.0	120	114	111
11	Center Panel Right				
12	Right Rear Door	113.6	115	106	120
13	Right Back Panel	114.8	125	97	122

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Mirror - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate but not attached