


General Information

Date & Time: 30, Jun, 2025 09:32

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	12,921
Registration No.	DBO4360	Chassis No.	MHKU3FE10PK005724
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Dropside
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	57.2	61	57	55
2	Boot Lid	53.2	68	49	43
3	Roof	50.0	45	55	50/49
4	Left Front Fender	50.0	56	52	42
5	Left Front Door	60.3	47	51	84
6	Center Panel Left	73.2	77	73	70
7	Left Rear Door				
8	Left Back Panel	44.4	43	46	44
9	Right Front Fender	60.1	62	57	62
10	Right Front Door	52.3	50	56	52
11	Center Panel Right	68.3	86	66	53
12	Right Rear Door				
13	Right Back Panel	47.1	54	46	42

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trim Other - Worked - Large / Trim Other - Worked - Large	Remarks (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch - Small / (R) Side Gate - Scratch - Medium / Rear Gate - Scratch - Large / (L) Side Gate - Scratch - Medium / Cargo Bed Floor - Scratch & Dent - Large / Cab Back Panel - Scratch - Large / (L) Center Panel - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / Front Panel - Scratch - Small / Roof - Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, no jack and tools, with spare tire, with LTO plate