

General Information

Date & Time: 09, Jul, 2025 12:38

Make	Chevrolet	Model	Colorado
YOM	2014	Odo Meter Reading	168,424
Registration No.	AAQ1697	Chassis No.	MMM148MK0EH608961
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.6	112	153	115
2	Boot Lid	139.6	137	138	144
3	Roof	127.7	144	137	118/112
4	Left Front Fender	173.0	222	142	155
5	Left Front Door	279.6	317	236	286
6	Center Panel Left				
7	Left Rear Door	279.3	318	257	263
8	Left Back Panel	214.6	197	209	238
9	Right Front Fender	172.6	165	178	175
10	Right Front Door	176.3	181	176	172
11	Center Panel Right				
12	Right Rear Door	173.3	175	185	160
13	Right Back Panel	202.3	229	180	198

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / Dashboard - Worn, Scratch, Cut, Crack - Small / Mat Other - Missing - Yes / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Floor Mat - Worked - Large / (R) Front Trim - Cut, Crack - Minimal</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch - Small / (L) Side Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Small / Roof - Rust, Corrosion - Small / (L) Side Gate - Modified - Medium / (R) Side Gate - Modified - Medium / (R) Rear Wheel, Cover - Cap Missing - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Window (each) - Stuck, Gap - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, no jack, incomplete tools, no spare tire, with LTO plate, scratches on tail light and headlight, suncrack headlights, driver side window issue</p>