

General Information

Date & Time: 28, Jun, 2025 17:40

Make	Hyundai	Model	Reina
YOM	2019	Odo Meter Reading	47,944
Registration No.	LAG3459	Chassis No.	LBECBAC8LW082925
CC	1.4	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	132.6	131	129	138
2	Boot Lid	117.0	113	110	128
3	Roof	98.8	100	108	96/91
4	Left Front Fender	114.0	121	118	103
5	Left Front Door	132.0	141	140	115
6	Center Panel Left				
7	Left Rear Door	124.0	124	132	116
8	Left Back Panel	131.3	121	135	138
9	Right Front Fender	104.7	106	113	95
10	Right Front Door	125.6	116	125	136
11	Center Panel Right				
12	Right Rear Door	119.3	114	121	123
13	Right Back Panel	113.6	118	120	103

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B		Exterior Evaluation : E	
			
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Ceiling - Grime - Medium / (R) Front Seat - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Minimal		Remarks (L) Rear Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Large / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small	
Frame Evaluation : A		Functional Evaluation : C	
Remarks Defects not found		Remarks Power Window (each) - Stuck, Gap - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist	

Inspector Notes

Horn issue. left and right rear door window switch issue. Without warranty booklet,jack and tools. With spare tire and seat cover. 1 key. With LTO plate.