


General Information

Date & Time: 09, Jul, 2025 17:30

Make	Hino	Model	315
YOM	2023	Odo Meter Reading	29,669
Registration No.	NHE2284	Chassis No.	JHHAGP6E30K003052
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Aluminum Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	83.3	99	74	77
2	Boot Lid	8.5	7	9	9
3	Roof	98.3	75	88	134/97
4	Left Front Fender	77.3	76	80	76
5	Left Front Door	78.4	78	75	83
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	6.9	6	8	7
9	Right Front Fender	73.0	74	74	72
10	Right Front Door	69.7	71	67	71
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	7.7	8	9	6

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Medium	Remarks Roof - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch & Dent - Medium / Rear Gate - Scratch - Medium / (L) Side Gate - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Small / Front Panel - Scratch - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet and LTO Plate, Jack and Sparetire, Incomplete Tools. scratch headlight and tail light. adhesive marks.