

General Information

Date & Time: 07, Jul, 2025 19:08

Make	Nissan	Model	NV350
YOM	2018	Odo Meter Reading	14,947
Registration No.	CAK4597	Chassis No.	JN1UC4E26Z0020374
CC	2.5	Transmission	A/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	161.6	143	170	172
2	Boot Lid	183.6	220	172	159
3	Roof	175.5	152	172	183/195
4	Left Front Fender	150.0	136	173	141
5	Left Front Door	153.6	178	119	164
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	170.3	169	167	175
9	Right Front Fender	149.3	119	167	162
10	Right Front Door	178.0	170	165	199
11	Center Panel Right	167.3	176	176	150
12	Right Rear Door	226.0	185	213	280
13	Right Back Panel	228.3	254	231	200

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / Ceiling - Grime - Medium</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Replaced - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Mirror - Scratch - Minimal / (R) Center Panel - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Rust, Corrosion - Minimal / Front Panel - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Large / Roof - Scratch & Dent - Large</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Shift Shock - Function - Weak / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack, no tools, with spare tire, with LTO plate, plate light issue, room lamp issue, shift shock issue, key slot issue</p>