

General Information

Date & Time: 09, Nov, 2024 14:46

Make	Toyota	Model	Vios
YOM	2021	Mileage	39,889
Registration No.	DBF3388	Chassis No.	PA1B18F32M4159451
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.0	132	130	128
2	Boot Lid	133.0	132	133	134
3	Roof	106.7	109	99	109/110
4	Left Front Fender	107.3	106	107	109
5	Left Front Door	116.6	114	121	115
6	Center Panel Left				
7	Left Rear Door	114.6	115	109	120
8	Left Back Panel	443.6	195	928	208
9	Right Front Fender	112.6	113	105	120
10	Right Front Door	121.3	116	128	120
11	Center Panel Right				
12	Right Rear Door	119.6	114	116	129
13	Right Back Panel	118.0	117	115	122

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium	Remarks (L) Rear Fender - Repair Traces - Yes / (R) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Dent - Small / (L) Front Fender, Molding - Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
reverse camera not function/hairline scratches/with spare tire&tool& jack/ with warranty booklet/ worn tires