

General Information

Date & Time: 14, Jul, 2025 16:25

Make	Chevrolet	Model	Colorado
YOM	2015	Odo Meter Reading	114,400
Registration No.	MCV5513	Chassis No.	MMM148MH0DH803942
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	147.3	145	170	127
2	Boot Lid	117.0	115	128	108
3	Roof	103.9	116	118	94/88
4	Left Front Fender	143.0	145	147	137
5	Left Front Door	144.6	131	148	155
6	Center Panel Left				
7	Left Rear Door	124.0	132	119	121
8	Left Back Panel	150.6	155	141	156
9	Right Front Fender	141.3	140	138	146
10	Right Front Door	129.0	127	127	133
11	Center Panel Right				
12	Right Rear Door	120.6	119	121	122
13	Right Back Panel	169.6	174	178	157

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / (R) Front Trim - Grime - Medium / (R) Rear Trim - Grime - Medium / (L) Rear Trim - Grime - Medium / Rear Seat - Cut, Crack - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Worn - Yes / Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Medium / Rear Gate - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Side Gate - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Large / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Window master switch issue. Parking brake issue. Headlight issue. With warranty booklet, spare tire and leather seat cover. Without jack and tools. 1 key. With LTO plate.</p>