

## General Information

Date & Time: 14, Jul, 2025 09:56

<b>Make</b>	Nissan	<b>Model</b>	NV350
<b>YOM</b>	2020	<b>Odo Meter Reading</b>	62,090
<b>Registration No.</b>	NFV6724	<b>Chassis No.</b>	JNTC2E26Z0062267
<b>CC</b>	2.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	162.0	156	184	146
2	Boot Lid	91.1	80	101	92
3	Roof	109.0	113	104	114/105
4	Left Front Fender	183.0	193	172	184
5	Left Front Door	169.3	179	168	161
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	163.6	181	163	147
9	Right Front Fender	192.3	176	226	175
10	Right Front Door	185.0	186	179	190
11	Center Panel Right	192.0	194	214	168
12	Right Rear Door	271.6	260	264	291
13	Right Back Panel	176.3	164	132	233

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	D	<b>Exterior Evaluation :</b>	E
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Floor Mat - Grime - Large / Ceiling - Grime - Large / Rear Seat - Grime - Large / (L) Front Floor Mat - Cut, Crack - Large / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium</p>		<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Center Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / Bonnet, Headlight - Repair mark - Yes / Bonnet, Headlight - Scratch &amp; Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Trunk Hood, Rear Gate - Repair mark - Yes / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / (L) Mirror - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Roof - Scratch &amp; Dent - Small</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
<p>Gap at front bumper. Wire cover at rear roof interior partially missing. left parklight and foglight issue. Possible flooding. With warranty booklet, spare tire and jack. Without tools. 1 key. With LTO plate</p>