

## General Information

Date & Time: 17, Jul, 2025 14:52

<b>Make</b>	Toyota	<b>Model</b>	Lite Ace
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	28,851
<b>Registration No.</b>	CCD1673	<b>Chassis No.</b>	MHKU3FE10PK005823
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Dropside
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	60.7	63	64	56
2	Boot Lid	47.9	52	47	45
3	Roof	47.8	47	52	45/48
4	Left Front Fender	44.5	42	44	48
5	Left Front Door	52.0	51	53	51
6	Center Panel Left	65.4	68	61	68
7	Left Rear Door				
8	Left Back Panel	45.6	40	50	48
9	Right Front Fender	55.3	63	54	48
10	Right Front Door	49.0	47	52	49
11	Center Panel Right	58.8	60	52	65
12	Right Rear Door				
13	Right Back Panel	45.3	47	48	41

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Small / Mat Other - Grime - Large / Ceiling - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Medium / (L) Front Seat - Grime - Small</p>	<p><b>Remarks</b> Cargo Bed Floor - Scratch &amp; Dent - Large / Cab Back Panel - Scratch &amp; Dent - Large / Rear Gate - Scratch &amp; Dent - Large / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Medium / (R) Center Panel - Scratch &amp; Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Side Gate - Scratch - Large / (L) Side Gate - Scratch &amp; Dent - Medium / Roof - Scratch &amp; Dent - Large / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Crack, Gap - Medium</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Crack signal light. With warranty booklet and spare tire. Without jack and tools. 1 key. With LTO plate.</p>