

## General Information

Date & Time: 18, Jul, 2025 13:32

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	10,752
<b>Registration No.</b>	NIN3559	<b>Chassis No.</b>	MHFAB1BY9P3052974
<b>CC</b>	1.5	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	MPV
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	103	103	105
2	Boot Lid	113.0	110	129	100
3	Roof	108.0	114	115	100/103
4	Left Front Fender	106.6	98	110	112
5	Left Front Door	107.0	102	105	114
6	Center Panel Left				
7	Left Rear Door	104.3	109	104	100
8	Left Back Panel	111.3	119	104	111
9	Right Front Fender	137.3	136	135	141
10	Right Front Door	101.4	103	102	99
11	Center Panel Right				
12	Right Rear Door	105.6	105	102	110
13	Right Back Panel	148.3	132	141	172

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Medium / (L) Front Floor Mat - Cigarette Burns - Burnt</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch - Minimal / (R) Mirror - Crack - Damaged</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With roof rack. Without warranty booklet, seat cover, and tools. With spare tire and jack. 1 key. With LTO plate.</p>