

General Information

Date & Time: 13, Nov, 2024 13:21

Make	Toyota	Model	Vios
YOM	2024	Mileage	2,125
Registration No.	NEY5380	Chassis No.	PA1B18F3XR4261782
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.0	125	109	123
2	Boot Lid	121.0	118	121	124
3	Roof	112.2	119	109	115/106
4	Left Front Fender	102.6	106	102	100
5	Left Front Door	110.3	111	107	113
6	Center Panel Left				
7	Left Rear Door	113.3	120	116	104
8	Left Back Panel	113.6	120	108	113
9	Right Front Fender	120.3	121	122	118
10	Right Front Door	116.0	120	119	109
11	Center Panel Right				
12	Right Rear Door	111.6	108	111	116
13	Right Back Panel	125.0	118	126	131

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Minimal	Remarks (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
swirlmarks and hairline scratches around the exterior.