

## General Information

Date & Time: 21, Jul, 2025 18:08

<b>Make</b>	Hino	<b>Model</b>	XZU710LN
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	26,982
<b>Registration No.</b>	NKF3932	<b>Chassis No.</b>	JHHUCP3F2RK056263
<b>CC</b>	4.0	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Aluminum Van
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	114	124	121
2	Boot Lid				
3	Roof	115.2	119	101	128/113
4	Left Front Fender				
5	Left Front Door	110.6	115	107	110
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	133.0	124	119	156
9	Right Front Fender				
10	Right Front Door	129.6	124	140	125
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	132.6	129	124	145

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Large / Sunvisor, Sunglass Holder - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium</p>	<p><b>Remarks</b> (L) Front Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Rear Corner Panel - Scratch - Small / (R) Side Gate - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Front Windshield - Scratch, Stone chip - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>crack windshield. Without warranty booklet and tools. With spare tire and jack. 1 key. With LTO plate.</p>