

General Information

Date & Time: 21, Jul, 2025 17:15

Make	Toyota	Model	Innova
YOM	2019	Odo Meter Reading	247,767
Registration No.	DAN8816	Chassis No.	PA2J8EM0K0070130
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Blackish Red Mica		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.3	135	137	131
2	Boot Lid	266.6	273	259	268
3	Roof	106.7	111	123	110/83
4	Left Front Fender	166.3	160	164	175
5	Left Front Door	117.6	120	121	112
6	Center Panel Left				
7	Left Rear Door	117.0	114	119	118
8	Left Back Panel	108.0	105	108	111
9	Right Front Fender	255.6	217	212	338
10	Right Front Door	97.0	97	99	95
11	Center Panel Right				
12	Right Rear Door	104.3	107	102	104
13	Right Back Panel	111.0	107	106	120

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Medium / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Seat - Grime - Medium / (R) Rear Trim - Grime - Medium / Rear Seat - Grime - Medium / Ceiling - Grime - Medium / (L) Rear Trim - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Cut, Crack - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Medium</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Roof - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Mirror - Faded(Color, Gloss) - Yes / (L) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Modified - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes
<p>Possible flooding. not original Innova Rims but Honda rims. aftermarket exhaust system. crack taillight. foglight issue. rear bumper and trunk door repaired. Left signal light issue. Without warranty booklet,jack,tools and seat cover. With spare tire. 1 key. With LTO plate.</p>