

## General Information

Date & Time: 24, Jul, 2025 12:39

<b>Make</b>	Toyota	<b>Model</b>	Hilux
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	25,971
<b>Registration No.</b>	NHM7630	<b>Chassis No.</b>	MR0JB8DD4P3224330
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	Black		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	106	116	118
2	Boot Lid	102.9	95	118	96
3	Roof	112.2	108	102	124/115
4	Left Front Fender	117.6	125	110	118
5	Left Front Door	104.3	105	105	103
6	Center Panel Left				
7	Left Rear Door	99.6	103	100	96
8	Left Back Panel	101.2	103	105	96
9	Right Front Fender	113.0	109	106	124
10	Right Front Door	101.6	107	100	98
11	Center Panel Right				
12	Right Rear Door	97.1	93	100	99
13	Right Back Panel	102.4	99	105	103

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>E</b></span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>            Mat Other - Missing - Yes / Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small</p>	<p><b>Remarks</b>            (R) Rear Door, Molding - Scratch - Large / (R) Rear Corner Panel - Scratch &amp; Dent - Medium / (R) Side Gate - Scratch - Large / Rear Gate - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Side Gate - Scratch - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch &amp; Dent - Medium / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Bonnet, Headlight - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / Roof - Scratch - Small / Cab Back Panel - Scratch - Small / Cargo Bed Floor - Scratch - Large</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b>            Defects not found</p>	<p><b>Remarks</b>            Spare Key - Issue - Unexist</p>

<b>Inspector Notes</b>
<p>No Bed cover. With warranty booklet and leather seat cover. Without spare tire, jack, and tools. 1 key. With LTO plate.</p>