

General Information

Date & Time: 25, Jul, 2025 09:35

Make	Nissan	Model	NV350
YOM	2018	Odo Meter Reading	59,247
Registration No.	NCT8603	Chassis No.	JN1TC2E26Z0050767
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	75.0	72	75	79
2	Boot Lid	119.3	123	108	127
3	Roof	72.9	82	81	66/64
4	Left Front Fender	78.5	81	76	79
5	Left Front Door	76.7	78	78	74
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	73.5	77	75	69
9	Right Front Fender	126.6	125	128	127
10	Right Front Door	73.8	68	70	84
11	Center Panel Right				
12	Right Rear Door	163.6	159	193	139
13	Right Back Panel	156.0	125	172	171

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Partially Missing - Yes / Mat Other - Missing - Yes / Rear Seat - Grime - Large / (R) Front Seat - Cut, Crack - Medium / Sunvisor, Sunglass Holder - Cut, Crack - Medium</p>	<p>Remarks (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Modified - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Modified - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Roof - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Possible flooding. Rear seat issue. Rear seat partially missing. watermarks at headlight. plate light issue. with warranty booklet and spare tire. Without jack and tools. 1 key. With LTO plate.</p>