

## General Information

Date & Time: 01, Aug, 2025 15:18

<b>Make</b>	Lexus	<b>Model</b>	ES350
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	55,215
<b>Registration No.</b>	DAP6890	<b>Chassis No.</b>	JTHBZ1B13M2016437
<b>CC</b>	3.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	101	104	106
2	Boot Lid	147.6	134	160	149
3	Roof	168.0	174	153	167/178
4	Left Front Fender	106.0	108	109	101
5	Left Front Door	163.0	166	167	156
6	Center Panel Left				
7	Left Rear Door	161.0	164	170	149
8	Left Back Panel	153.0	144	159	156
9	Right Front Fender	99.8	109	104	87
10	Right Front Door	169.3	156	180	172
11	Center Panel Right				
12	Right Rear Door	160.6	154	167	161
13	Right Back Panel	153.3	160	152	148

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Floor Mat - Worked - Small</p>	<p><b>Remarks</b> (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Roof - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate and Spare tire and Jack, Incomplete Tools/ No warranty booklet and scratch headlight and tail light/ left side mirror don't retract / warning lamps on/Rear camera detection unavailable/ vanity light.</p>