

General Information

Date & Time: 04, Aug, 2025 08:57

Make	Suzuki	Model	Ciaz
YOM	2019	Odo Meter Reading	47,532
Registration No.	NFW2062	Chassis No.	MMSVCC41S5KR104710
CC	1.4	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	86.9	86	89	86
2	Boot Lid	99.3	107	86	105
3	Roof	93.2	97	89	89/99
4	Left Front Fender	208.3	156	332	137
5	Left Front Door	90.3	96	89	87
6	Center Panel Left				
7	Left Rear Door	135.6	126	130	151
8	Left Back Panel	110.6	121	102	109
9	Right Front Fender	142.0	139	145	142
10	Right Front Door	90.2	91	90	90
11	Center Panel Right				
12	Right Rear Door	91.7	93	89	93
13	Right Back Panel	99.4	98	94	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / (L) Front Seat - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small	Remarks (L) Front Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Hood prop issue. Scratches on headlights. Grime at trunk room. Without warranty booklet and tools. With spare tire and jack. 1 key. With LTO plate.