

General Information

Date & Time: 18, Nov, 2024 09:56

Make	Toyota	Model	Vios
YOM	2022	Mileage	24,634
Registration No.	NIE9625	Chassis No.	PA1B18F32N4187445
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	106	105	123
2	Boot Lid	107.6	109	110	104
3	Roof	99.5	106	95	98/100
4	Left Front Fender	106.6	106	109	105
5	Left Front Door	103.0	106	102	101
6	Center Panel Left				
7	Left Rear Door	103.6	109	101	101
8	Left Back Panel	107.1	111	113	97
9	Right Front Fender	100.9	97	105	101
10	Right Front Door	98.8	97	97	102
11	Center Panel Right				
12	Right Rear Door	104.6	103	104	107
13	Right Back Panel	110.3	108	108	115

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Medium / Overall Interior - Animal Hair - Yes / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Dent - Minimal / (R) Front Fender, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

hairline scratches around the exterior. without spare tire and tools. without user manual and warranty booklet