

## General Information

Date & Time: 11, Aug, 2025 13:36

<b>Make</b>	Toyota	<b>Model</b>	Rush
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	26,413
<b>Registration No.</b>	DBP1612	<b>Chassis No.</b>	MHKE8FF3PRK061827
<b>CC</b>	1.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	158.0	151	159	164
2	Boot Lid	128.0	132	127	125
3	Roof	147.7	144	171	145/131
4	Left Front Fender	154.6	161	150	153
5	Left Front Door	159.6	159	158	162
6	Center Panel Left				
7	Left Rear Door	151.6	159	151	145
8	Left Back Panel	135.3	152	130	124
9	Right Front Fender	164.6	171	166	157
10	Right Front Door	130.0	139	127	124
11	Center Panel Right				
12	Right Rear Door	133.0	130	135	134
13	Right Back Panel	127.3	126	123	133

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>          Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / Mat Other - Crinkle - Medium / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes</p>	<p><b>Remarks</b>          Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch &amp; Dent - Large / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch &amp; Dent - Medium / (L) Mirror - Crack - Damaged</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b>          Defects not found</p>	<p><b>Remarks</b>          Retractable Mirror - Issue - Yes / Spare Key - Issue - Unexist</p>

<b>Inspector Notes</b>
Damaged left side mirror. Without warranty booklet and tools. With spare tire,jack and seat cover. 1 key. With LTO plate.