

General Information

Date & Time: 18, Aug, 2025 15:05

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	88,610
Registration No.	DBH5255	Chassis No.	PA1B18F34P4208136
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	219.0	219	234	204
2	Boot Lid	107.3	105	106	111
3	Roof	100.7	103	101	99/100
4	Left Front Fender	1,104.6	962	1,245	1,107
5	Left Front Door	97.8	98	97	99
6	Center Panel Left				
7	Left Rear Door	106.0	112	104	102
8	Left Back Panel	151.0	143	170	140
9	Right Front Fender	198.3	193	208	194
10	Right Front Door	103.4	114	97	99
11	Center Panel Right				
12	Right Rear Door	108.6	112	104	110
13	Right Back Panel	113.6	101	108	132

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes</p>		<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Crack, Gap - Medium / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Dent - Small / Bonnet, Headlight - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Crack, Gap - Small / Trunk Hood, Rear Gate - Dent - Small / Roof - Scratch - Small</p>	
Frame Evaluation :	B	Functional Evaluation :	A
<p>Remarks Front Cross Member Support - Condition of Welding ? - Yes</p>		<p>Remarks Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate/No spare tire/No jack and tools/No reverse camera/With warranty booklet/ No spare key/dome light issue/headlight issue