

General Information

Date & Time: 18, Aug, 2025 08:51

Make	Toyota	Model	Hiace
YOM	2024	Odo Meter Reading	27,566
Registration No.	NHM4590	Chassis No.	JTFJT02P4P5036123
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.0	120	124	122
2	Boot Lid	113.3	112	113	115
3	Roof	104.9	116	105	103/96
4	Left Front Fender	149.6	180	134	135
5	Left Front Door	120.0	114	122	124
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	121.3	131	116	117
9	Right Front Fender	138.0	133	134	147
10	Right Front Door	114.6	116	113	115
11	Center Panel Right	124.0	133	116	123
12	Right Rear Door	125.3	125	122	129
13	Right Back Panel	131.0	127	126	140

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Trim - Cut, Crack - Small / (L) Front Floor Mat - Worked - Small / Glove Box - Worn, Scratch, Cut, Crack - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Small / Mat Other - Worked - Small / (L) Front Trim - Cut, Crack - Minimal / Sunvisor, Sunglass Holder - Missing - Yes</p>	<p>Remarks (R) Mirror - Crack - Cracks / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Minimal / Front Panel - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes
<p>with warranty booklet, with jack and tools, with spare tire and LTO PLATE, damaged lto plate, scratches on headlight and tail light, abnormal noise on under chassis, right side mirror replaced</p>