


## General Information

Date & Time: 18, Aug, 2025 17:17

<b>Make</b>	Toyota	<b>Model</b>	Veloz
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	16,563
<b>Registration No.</b>	NIU8315	<b>Chassis No.</b>	MHFAB1BY8R3085046
<b>CC</b>	1.5	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.6	116	131	115
2	Boot Lid	108.3	111	115	99
3	Roof	126.0	128	148	113/115
4	Left Front Fender	111.6	114	112	109
5	Left Front Door	121.6	115	121	129
6	Center Panel Left				
7	Left Rear Door	119.6	125	115	119
8	Left Back Panel	110.5	133	85	114
9	Right Front Fender	114.6	110	118	116
10	Right Front Door	111.3	115	109	110
11	Center Panel Right				
12	Right Rear Door	113.0	115	108	116
13	Right Back Panel	129.3	113	129	146

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small</p>	<p><b>Remarks</b> (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch &amp; Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch &amp; Dent - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Defects not found</p>

<p><b>Inspector Notes</b></p>
<p>With LTO plate and warranty booklet and Sparetire and Jack, Incomplete Tools. Scratch headlight and tail light.</p>