

## General Information

Date & Time: 20, Aug, 2025 13:19

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	46,303
<b>Registration No.</b>	CAX2927	<b>Chassis No.</b>	MHKM5EF2FMK029670
<b>CC</b>	1.3	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Wagon
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	110	117	113
2	Boot Lid	103.1	107	98	105
3	Roof	106.2	96	105	117/107
4	Left Front Fender	100.6	105	101	96
5	Left Front Door	107.6	107	106	110
6	Center Panel Left				
7	Left Rear Door	95.8	98	99	91
8	Left Back Panel	91.6	93	94	88
9	Right Front Fender	102.0	109	99	98
10	Right Front Door	105.3	109	100	107
11	Center Panel Right				
12	Right Rear Door	96.7	96	95	99
13	Right Back Panel	101.9	99	106	101

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>          Mat Other - Worked - Small / Ceiling - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium / (L) Front Trim - Grime - Medium / Rear Seat - Grime - Minimal / (R) Front Trim - Grime - Minimal</p>	<p><b>Remarks</b>          (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch &amp; Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b>          Defects not found</p>	<p><b>Remarks</b>          Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>no warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on headlight and tail light, brake lights issue</p>