

General Information

Date & Time: 25, Nov, 2024 13:24

Make	Toyota	Model	Innova
YOM	2021	Mileage	114,372
Registration No.	DAT5550	Chassis No.	PA2CA8EMXL0085423
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	MPV
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.0	120	126	126
2	Boot Lid	197.6	133	218	242
3	Roof	92.1	90	89	106/83
4	Left Front Fender	156.0	104	152	212
5	Left Front Door	98.3	102	99	94
6	Center Panel Left				
7	Left Rear Door	94.8	97	95	92
8	Left Back Panel	103.0	103	106	100
9	Right Front Fender	120.3	145	109	107
10	Right Front Door	99.3	96	101	101
11	Center Panel Right				
12	Right Rear Door	99.7	100	100	100
13	Right Back Panel	108.0	99	107	118

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain Remarks (L) Front Floor Mat - Grime - Medium / Ceiling - Cigarette Burns - Burnt Minimal / Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Rear End Panel - Replaced - Yes / Bonnet, Headlight - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / (R) Front Fender, Molding - Dent - Medium / (R) Front Door, Molding - Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Crack, Gap - Large / Trunk Hood, Rear Gate - Dent - Medium / (L) Front Fender, Molding - Crack, Gap - Large / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Roof - Dent - Small / (L) Center Panel - Scratch - Small
Frame Evaluation : B	Functional Evaluation : E
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Power Steering - Issue - Yes / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, user manual. incomplete tools. front driver side power window automatic malfunction.