

## General Information

Date & Time: 25, Nov, 2024 11:05

<b>Make</b>	Toyota	<b>Model</b>	Innova
<b>YOM</b>	2020	<b>Mileage</b>	28,568
<b>Registration No.</b>	NFZ8472	<b>Chassis No.</b>	PA2JA8EMXL0077992
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	MPV
<b>Colour</b>	BLACKISH RED MICA		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	105	113	110
2	Boot Lid	96.9	99	95	96
3	Roof	90.8	99	93	86/86
4	Left Front Fender	91.3	92	94	89
5	Left Front Door	101.2	100	98	106
6	Center Panel Left				
7	Left Rear Door	97.0	95	95	101
8	Left Back Panel	100.0	98	103	99
9	Right Front Fender	93.5	90	94	97
10	Right Front Door	93.8	96	95	91
11	Center Panel Right				
12	Right Rear Door	92.4	89	91	97
13	Right Back Panel	98.6	98	100	98

Overall Evaluation :

**D**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>E</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b></p> <p>Rear Seat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Switchs - Missing - Yes / Switchs - Missing - Yes / Trim Other - Missing - Yes / Trim Other - Missing - Yes / Trim Other - Missing - Yes / Glove Box - Loose, Deformed - Large / Dashboard - Loose, Deformed - Large / Display, Audio System - Missing - Yes / Room Mirror - Missing - Yes / (R) Front Seat Head Rest - Missing - Yes / (L) Front Seat Head Rest - Missing - Yes / Rear Seat Head Rest - Missing - Yes / Sunvisor, Sunglass Holder - Missing - Yes / Room Mirror - Missing - Yes / Switchs - Missing - Yes / (L) Front Trim - Loose, Deformed - Large / (L) Rear Trim - Loose, Deformed - Medium / (R) Front Trim - Loose, Deformed - Large / (R) Rear Trim - Loose, Deformed - Large / Seat belt Other - Loose, Deformed - Large</p>	<p><b>Remarks</b></p> <p>(R) Rear Wheel, Cover - Cap Missing - Yes / (R) Front Wheel, Cover - Cap Missing - Yes / (L) Front Wheel, Cover - Cap Missing - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Small / (L) Rear Fender, Molding - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof Spoiler, Molding - Partially Missing - Yes</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>D</b></span>
<p><b>Remarks</b></p> <p>Defects not found</p>	<p><b>Remarks</b></p> <p>Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>half of the interior trims are missng/ windows and door lock switch missing/ no multimedia/ no hydraulic latch on the rear hatch/ no warranty booklet/ no tools/ no jack/ no spare tire</p>