

General Information

Date & Time: 01, Sep, 2025 10:40

Make	Suzuki	Model	Ertiga
YOM	2024	Odo Meter Reading	29,924
Registration No.	NNV9117	Chassis No.	MHYNC32S6RJ106565
CC	1.5	Transmission	A/T
Fuel Type	Hybrid	Type of Body	Wagon
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.0	98	96	97
2	Boot Lid	93.2	88	95	97
3	Roof	96.6	88	90	100/109
4	Left Front Fender	95.0	94	90	101
5	Left Front Door	103.2	109	95	106
6	Center Panel Left				
7	Left Rear Door	108.3	115	102	108
8	Left Back Panel	153.0	114	117	228
9	Right Front Fender	93.7	104	92	85
10	Right Front Door	113.0	117	109	113
11	Center Panel Right				
12	Right Rear Door	111.3	111	104	119
13	Right Back Panel	99.8	100	96	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Large / Rear Seat - Grime - Large / (R) Rear Trim - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Ceiling - Grime - Medium</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Bonnet, Headlight - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Large / Trunk Hood, Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Dent - Medium / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / Roof - Dent - Medium / (L) Rear Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with warranty booklet/No reverse camera/with spare key/right front seat back damage/ foul smell/ possible flooding/radiator issue</p>