

General Information

Date & Time: 10, Sep, 2025 09:00

Make	Toyota	Model	Lite Ace
YOM	2023	Odo Meter Reading	32,332
Registration No.	EAG3845	Chassis No.	MHKU3FE10NK002410
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	51.3	51	50	54
2	Boot Lid	48.8	46	59	41
3	Roof	49.4	44	48	40/65
4	Left Front Fender	42.4	39	43	46
5	Left Front Door	47.8	45	51	47
6	Center Panel Left	57.9	73	54	48
7	Left Rear Door	41.0	29	29	65
8	Left Back Panel	34.6	32	39	34
9	Right Front Fender	54.5	55	50	59
10	Right Front Door	47.2	40	54	48
11	Center Panel Right	65.6	74	65	59
12	Right Rear Door	41.5	44	44	36
13	Right Back Panel	43.9	43	43	47

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / (R) Front Trim - Worked - Small / Overall Interior - Smell - Yes / Dashboard - Worn, Scratch, Cut, Crack - Small / Glove Box - Worn, Scratch, Cut, Crack - Small / Mat Other - Worked - Small / (L) Front Trim - Worked - Large / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small</p>	<p>Remarks Cargo Bed Floor - Rust, Corrosion - Large / Rear Gate - Scratch & Dent - Large / (R) Side Gate - Scratch - Large / (L) Side Gate - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Rust, Corrosion - Medium / (R) Front Door, Molding - Scratch - Large / Roof - Dent - Large / Front Panel - Scratch - Medium / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large</p>
Frame Evaluation : D	Functional Evaluation : A
<p>Remarks Left Front Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, no warranty booklet, no jack and tools, with spare tire, damaged tail light and headlights</p>