

## General Information

Date & Time: 10, Sep, 2025 10:18

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	27,773
<b>Registration No.</b>	NIG2512	<b>Chassis No.</b>	PA1B18F38N4196604
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	105	111	112
2	Boot Lid	102.6	102	104	102
3	Roof	93.9	110	88	89/89
4	Left Front Fender	101.0	110	93	100
5	Left Front Door	106.6	106	104	110
6	Center Panel Left				
7	Left Rear Door	105.6	110	107	100
8	Left Back Panel	109.6	118	108	103
9	Right Front Fender	94.5	94	96	95
10	Right Front Door	94.0	88	98	96
11	Center Panel Right				
12	Right Rear Door	98.5	96	100	100
13	Right Back Panel	94.3	89	92	102

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>C</b>
	
<b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain	<b>A</b> : Scratch <b>AU</b> : Scratch & Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust & Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap
<b>Remarks</b> Mat Other - Grime - Small / (R) Front Seat - Grime - Medium / (L) Front Seat - Worn - Yes / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal / Ceiling - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal	<b>Remarks</b> (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal
<b>Frame Evaluation :</b>	<b>A</b>
<b>Remarks</b> Defects not found	<b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light