

General Information

Date & Time: 03, Dec, 2024 08:46

Make	Toyota	Model	Wigo
YOM	2023	Mileage	21,161
Registration No.	DBG8637	Chassis No.	MHKA4DF5FNJ078657
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.0	94	107	88
2	Boot Lid	96.7	89	103	99
3	Roof	89.1	78	102	85/91
4	Left Front Fender	104.6	100	109	105
5	Left Front Door	97.9	100	105	89
6	Center Panel Left				
7	Left Rear Door	99.7	99	101	99
8	Left Back Panel	95.6	96	104	87
9	Right Front Fender	102.4	103	106	98
10	Right Front Door	97.1	93	100	98
11	Center Panel Right				
12	Right Rear Door	96.0	99	97	92
13	Right Back Panel	96.1	88	99	101

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / Trunk Room - Traces of Adhesive Tape - Yes / Mat Other - Missing - Yes	Remarks Bonnet - Repair Traces - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes

hairline scratches around the exterior. no warranty booklet, user manual and tools.