

## General Information

Date & Time: 06, Sep, 2025 15:53

<b>Make</b>	Toyota	<b>Model</b>	Alphard
<b>YOM</b>	2020	<b>Odo Meter Reading</b>	9,972
<b>Registration No.</b>	NEL1771	<b>Chassis No.</b>	JNTNGZ3D5LL8031030
<b>CC</b>	3.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Van
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.0	127	152	123
2	Boot Lid	117.0	113	127	111
3	Roof	116.5	121	123	109/113
4	Left Front Fender	124.0	116	132	124
5	Left Front Door	151.6	137	144	174
6	Center Panel Left				
7	Left Rear Door	135.0	141	133	131
8	Left Back Panel	127.6	135	121	127
9	Right Front Fender	116.6	122	123	105
10	Right Front Door	145.6	149	146	142
11	Center Panel Right				
12	Right Rear Door	138.0	139	139	136
13	Right Back Panel	128.3	125	127	133

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	A	<b>Exterior Evaluation :</b>	B
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / Ceiling - Grime - Small</p>		<p><b>Remarks</b> (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Roof - Scratch - Small / Bonnet, Headlight - Dent - Minimal</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
<p>With LTO plate and warranty booklet and Sparetire and, Incomplete Tools, No Jack and scratch headlight and tail light. double registration under two records.</p>