

## General Information

Date & Time: 10, Sep, 2025 15:08

<b>Make</b>	Toyota	<b>Model</b>	Rush
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	87,103
<b>Registration No.</b>	NFH5664	<b>Chassis No.</b>	MHKE8FF3PNK042028
<b>CC</b>	1.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	117	120	119
2	Boot Lid	117.6	115	125	113
3	Roof	115.5	118	118	114/112
4	Left Front Fender	209.6	229	226	174
5	Left Front Door	118.6	114	118	124
6	Center Panel Left				
7	Left Rear Door	118.0	116	113	125
8	Left Back Panel	116.3	119	113	117
9	Right Front Fender	116.3	117	115	117
10	Right Front Door	114.6	116	114	114
11	Center Panel Right				
12	Right Rear Door	115.0	116	114	115
13	Right Back Panel	112.6	113	112	113

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Trunk Room - Worn, Scratch, Cut, Crack - Medium / (L) Rear Trim - Worked - Small / Rear Seat - Grime - Medium / (R) Rear Trim - Worked - Small / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Medium / (R) Front Floor Mat - Missing - Yes / Display, Audio System - Missing - Yes / Steering Wheel - Worn, Peel, Crack - Medium / Ceiling - Grime - Medium / (L) Front Floor Mat - Missing - Yes / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small	<b>Remarks</b> (L) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Dent - Minimal / (L) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Modified - Medium / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Bonnet, Headlight - Scratch - Small / Roof - Dent - Small
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
with LTO plate, with warranty booklet, no jack and tools, with spare tire, scratches on headlight, damaged tail light, missing head unit, hazard switch issue, HPG Recover