

## General Information

Date & Time: 12, Sep, 2025 15:38

Make	MG	Model	MG 5
YOM	2022	Odo Meter Reading	40,209
Registration No.	LAK8037	Chassis No.	LSJA36E38NZ017924
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.3	129	112	135
2	Boot Lid	122.0	118	125	123
3	Roof	118.0	123	113	125/111
4	Left Front Fender	127.0	134	125	122
5	Left Front Door	136.6	146	129	135
6	Center Panel Left				
7	Left Rear Door	129.3	128	127	133
8	Left Back Panel	126.0	128	133	117
9	Right Front Fender	124.6	117	130	127
10	Right Front Door	127.0	129	118	134
11	Center Panel Right				
12	Right Rear Door	126.3	123	124	132
13	Right Back Panel	128.6	107	135	144

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>D</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Rear Seat - Grime - Small / Ceiling - Grime - Small / Overall Interior - Smell - Yes / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Worked - Small / Mat Other - Worked - Small</p>	<p><b>Remarks</b> (L) Mirror - Scratch - Minimal / (L) Mirror - Crack - Damaged / (L) Rear Door, Molding - Scratch &amp; Dent - Minimal / (L) Front Door, Molding - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch &amp; Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch &amp; Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Roof - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With LTO plate and Spare tire and Jack and Incomplete Tools, No warranty booklet and scratch headlight and tail light, Crack headlight left side, possible flooded, unusual vibration on engine, asphalt marks on vehicle. room light issue</p>