

General Information

Date & Time: 15, Sep, 2025 10:45

Make	Mitsubishi	Model	Mirage
YOM	2023	Odo Meter Reading	13,793
Registration No.	DBH6951	Chassis No.	PAEA123TJPPA008177
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	121	108	121
2	Boot Lid	101.6	112	94	99
3	Roof	92.8	90	95	86/100
4	Left Front Fender	100.3	103	98	100
5	Left Front Door	99.5	99	100	100
6	Center Panel Left				
7	Left Rear Door	126.5	95	140	145
8	Left Back Panel	166.0	172	182	144
9	Right Front Fender	99.3	95	97	106
10	Right Front Door	97.7	97	97	100
11	Center Panel Right				
12	Right Rear Door	95.3	97	88	101
13	Right Back Panel	111.0	103	113	117

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Trunk Room - Loose, Deformed - Small</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (L) Rear Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Dent - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with Sparetire, No Tools and Jack and Warranty booklet and LTO Plate, scratch headlight and tail light, worn tires and Sparetire. No spare key.</p>