

## General Information

Date & Time: 15, Sep, 2025 16:34

<b>Make</b>	Kia	<b>Model</b>	Soluto
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	34,505
<b>Registration No.</b>	NHL8936	<b>Chassis No.</b>	LJD0AA29BR0240151
<b>CC</b>	1.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Beige		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	187.0	181	199	181
2	Boot Lid	162.0	160	163	163
3	Roof	155.0	161	150	154/155
4	Left Front Fender	141.3	135	140	149
5	Left Front Door	143.6	141	142	148
6	Center Panel Left				
7	Left Rear Door	144.0	152	146	134
8	Left Back Panel	150.3	154	144	153
9	Right Front Fender	146.3	150	149	140
10	Right Front Door	168.6	167	173	166
11	Center Panel Right				
12	Right Rear Door	145.0	133	150	152
13	Right Back Panel	152.6	154	148	156

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>B</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Rear Seat - Grime - Medium / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Ceiling - Crinkle - Minimal / Overall Interior - Smell - Yes / Mat Other - Missing - Yes</p>		<p><b>Remarks</b> Bonnet - Repair Traces - Yes / (L) Rear Door, Molding - Scratch &amp; Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Minimal / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch &amp; Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Bonnet, Headlight - Repair mark - Yes</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
With Sparetire and Jack, No Tools and warranty booklet LTO plate, no headlight, foul smell, No spare key,