

General Information

Date & Time: 20, Sep, 2025 13:57

Make	Hino	Model	XZU600LA
YOM	2021	Odo Meter Reading	79,408
Registration No.	CAX5984	Chassis No.	PA4ACN4F2M9000405
CC	4.0	Transmission	A/T
Fuel Type	Diesel	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	64.1	66	62	64
2	Boot Lid	354.3	478	341	244
3	Roof	75.5	77	73	71/81
4	Left Front Fender	61.1	60	62	61
5	Left Front Door	69.2	68	64	76
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	327.3	228	488	266
9	Right Front Fender	61.1	62	63	58
10	Right Front Door	65.7	69	63	66
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	212.3	266	291	80

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Rear Seat - Missing - Yes / Mat Other - Missing - Yes	Remarks (R) Front Door - Repair Traces - Yes / Front Panel - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Fender, Molding - Scratch - Small / Front Panel - Dent - Small / (L) Side Gate - Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / Front Windshield - Damaged - Small / (R) Side Gate - Scratch - Medium / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Cab Back Panel - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With LTO plate and Sparetire and Jack and Incomplete Tools, scratch headlight and tail light and plate light busted, No spare key.