

## General Information

Date & Time: 24, Sep, 2025 12:34

<b>Make</b>	Toyota	<b>Model</b>	Hilux
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	62,112
<b>Registration No.</b>	EAG6828	<b>Chassis No.</b>	MR0JB8DD9P3221522
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.0	114	123	123
2	Boot Lid	111.6	100	121	114
3	Roof	115.2	115	108	118/120
4	Left Front Fender	122.6	134	120	114
5	Left Front Door	111.3	117	108	109
6	Center Panel Left				
7	Left Rear Door	109.0	108	106	113
8	Left Back Panel	105.3	108	104	104
9	Right Front Fender	102.7	104	106	98
10	Right Front Door	111.6	115	110	110
11	Center Panel Right				
12	Right Rear Door	102.3	99	103	105
13	Right Back Panel	113.0	116	107	116

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold;">E</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Rear Seat - Grime - Large / (R) Rear Trim - Grime - Medium / (L) Rear Trim - Grime - Medium / (R) Front Trim - Grime - Large / (L) Front Trim - Grime - Large / (R) Front Seat - Grime - Large / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Large / (L) Front Seat - Grime - Medium</p>	<p><b>Remarks</b> Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (L) Front Fender, Molding - Crack, Gap - Medium / (L) Front Door, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Side Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Rear Gate - Scratch &amp; Dent - Medium / (R) Side Gate - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch &amp; Dent - Small / Roof - Scratch - Medium / Bonnet, Headlight - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>possible flooding/ with warranty booklet and spare tire/ no tools and jack/ with LTO plate</p>