

General Information

Date & Time: 18, Dec, 2024 13:25

Make	Toyota	Model	Innova
YOM	2022	Mileage	96,934
Registration No.	NFE3732	Chassis No.	PA2JA8EM1N0109179
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	113	109	103
2	Boot Lid	97.1	97	100	95
3	Roof	95.7	114	88	91/90
4	Left Front Fender	99.7	93	98	108
5	Left Front Door	117.3	113	127	112
6	Center Panel Left				
7	Left Rear Door	113.6	113	122	106
8	Left Back Panel	105.2	114	102	100
9	Right Front Fender	95.2	94	96	96
10	Right Front Door	94.9	95	96	94
11	Center Panel Right				
12	Right Rear Door	103.6	122	92	97
13	Right Back Panel	109.2	109	119	100

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Large	Remarks (R) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes

Inspector Notes

left low beam headlight not working/ reverse camera not working/ with warranty booklet/ with jack and tools/ with spare tire