

## General Information

Date & Time: 16, Dec, 2025 20:19

<b>Make</b>	Suzuki	<b>Model</b>	Dzire
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	9,627
<b>Registration No.</b>	GBJ3100	<b>Chassis No.</b>	MBHZF63S8SG585520
<b>CC</b>	1.2	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	111	105	114
2	Boot Lid	91.1	96	89	88
3	Roof	111.7	105	103	116/123
4	Left Front Fender	108.0	107	113	104
5	Left Front Door	112.6	117	114	107
6	Center Panel Left				
7	Left Rear Door	103.9	112	109	91
8	Left Back Panel	101.2	110	102	92
9	Right Front Fender	105.6	102	111	104
10	Right Front Door	111.6	112	111	112
11	Center Panel Right				
12	Right Rear Door	105.0	103	106	106
13	Right Back Panel	109.3	103	110	115

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Small</p>	<p><b>Remarks</b> Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (L) Front Door, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Defects not found</p>

<p><b>Inspector Notes</b></p>
<p>no LTO plate/ with jack and tools/ with warranty booklet and spare tire/</p>