

## General Information

Date & Time: 10, Nov, 2025 17:43

<b>Make</b>	Toyota	<b>Model</b>	Hiace
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	28,416
<b>Registration No.</b>	DBQ7247	<b>Chassis No.</b>	JTFNAFAP9P8040257
<b>CC</b>	2.8	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	91.7	102	86	88
2	Boot Lid	85.5	83	86	88
3	Roof	97.5	99	98	101/92
4	Left Front Fender	82.7	80	86	82
5	Left Front Door	142.0	148	134	144
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	120.0	132	111	117
9	Right Front Fender	83.5	83	86	82
10	Right Front Door	148.0	157	149	138
11	Center Panel Right	149.3	139	156	153
12	Right Rear Door	208.3	190	206	229
13	Right Back Panel	232.3	202	207	288

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>D</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Small / Mat Other - Missing - Yes / (L) Front Seat - Grime - Minimal</p>	<p><b>Remarks</b> (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Center Panel - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Large / (R) Mirror - Crack - Damaged</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Right side mirror crack. With warranty booklet. Without spare tire,jack and tools. 1 key. With LTO plate.</p>