

## General Information

Date & Time: 23, Oct, 2025 15:22

<b>Make</b>	Toyota	<b>Model</b>	Hiace
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	99,236
<b>Registration No.</b>	NEX9561	<b>Chassis No.</b>	JTFJT02P9M5028384
<b>CC</b>	3.0	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	80.4	79	88	74
2	Boot Lid	77.3	79	77	77
3	Roof	67.9	75	67	60/70
4	Left Front Fender	82.7	82	83	83
5	Left Front Door	66.4	73	61	65
6	Center Panel Left	61.0	66	63	54
7	Left Rear Door	69.2	69	70	69
8	Left Back Panel	66.4	68	66	65
9	Right Front Fender	80.3	77	80	85
10	Right Front Door	66.3	64	68	67
11	Center Panel Right	71.1	79	71	64
12	Right Rear Door	71.0	73	73	67
13	Right Back Panel	80.2	71	88	81

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Medium / (L) Front Trim - Grime - Small / Ceiling - Grime - Small	<b>Remarks</b> (R) Front Door, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Center Panel - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / Roof - Scratch - Small
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
with LTO plate/with spare tire/No reverse camera/No spare key/with warranty booklet/No jack and No tools/left and right tail light small crack and scratch/No fog light/plate light issue/audio radio issue