

General Information

Date & Time: 10, Oct, 2025 16:05

Make	Mitsubishi	Model	Mirage
YOM	2019	Odo Meter Reading	58,984
Registration No.	NDP8052	Chassis No.	PAEA13TXKKA007483
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.0	102	104	106
2	Boot Lid	108.0	105	108	111
3	Roof	413.2	158	314	530/651
4	Left Front Fender	645.0	123	593	1,219
5	Left Front Door	111.3	112	107	115
6	Center Panel Left				
7	Left Rear Door	191.3	155	184	235
8	Left Back Panel	258.6	265	268	243
9	Right Front Fender	112.6	117	115	106
10	Right Front Door	154.3	158	150	155
11	Center Panel Right				
12	Right Rear Door	146.6	144	141	155
13	Right Back Panel	267.0	142	116	543

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Large / Dashboard - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small / Rear Seat - Partially Missing - Yes</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Roof - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / (R) Rear Fender, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / Roof - Scratch - Medium</p>
Frame Evaluation : C	Functional Evaluation : C
<p>Remarks Front Cross Member Support - Condition of Welding ? - Yes / Left Front Inside Panel (Front Side) - Condition of Welding, Hardness and Shape of Sealant ? - Yes</p>	<p>Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>

Inspector Notes
<p>with LTO plate and Sparetire, No Tools and Jack and Warranty booklet, scratch headlight and tail light, Worn Tires and Sparetire, No spare key, no reverse camera, foul smell, possible flooded, Room light issue, plate light issue, Abnormal vibration on engine And transmission abnormal noise. abnormal noise when running.</p>