

## General Information

Date & Time: 30, Oct, 2025 13:15

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	23,828
<b>Registration No.</b>	EAG4894	<b>Chassis No.</b>	PA1B18F38P4217101
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	276.0	328	258	242
2	Boot Lid	120.6	115	121	126
3	Roof	113.5	118	106	116/114
4	Left Front Fender	105.7	115	98	104
5	Left Front Door	107.6	104	103	116
6	Center Panel Left				
7	Left Rear Door	119.3	130	126	102
8	Left Back Panel	120.0	115	112	133
9	Right Front Fender	252.6	104	108	546
10	Right Front Door	110.3	109	108	114
11	Center Panel Right				
12	Right Rear Door	114.6	121	100	123
13	Right Back Panel	126.0	109	118	151

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>E</b>	<b>Exterior Evaluation :</b>	<b>E</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (L) Rear Trim - Grime - Large / (R) Rear Trim - Grime - Large / Rear Seat - Grime - Large / (R) Front Trim - Grime - Large / (R) Front Seat - Grime - Large / Glove Box - Loose, Deformed - Large / (L) Front Trim - Grime - Large / Carpet - Worked - Large</p>		<p><b>Remarks</b> (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Dent - Large / (L) Rear Fender, Molding - Scratch &amp; Dent - Medium / Trunk Hood, Rear Gate - Modified - Large / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Modified - Large / (R) Rear Fender, Molding - Scratch &amp; Dent - Large / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Scratch &amp; Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Large</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>B</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
possible flooding/ no spare tire and tools/ no jack and LTO plate/ with warranty booklet/