

## General Information

Date & Time: 16, Dec, 2024 14:07

<b>Make</b>	Toyota	<b>Model</b>	Land Cruiser
<b>YOM</b>	2018	<b>Mileage</b>	66,868
<b>Registration No.</b>	NBM5048	<b>Chassis No.</b>	JTMHV01J6H4229797
<b>CC</b>	4.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	SUV
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	112	117	119
2	Boot Lid	133.6	123	140	138
3	Roof	117.4	108	97	133/132
4	Left Front Fender	121.0	120	121	122
5	Left Front Door	123.0	128	124	117
6	Center Panel Left				
7	Left Rear Door	124.3	129	128	116
8	Left Back Panel	112.3	115	110	112
9	Right Front Fender	118.6	128	118	110
10	Right Front Door	133.0	136	130	133
11	Center Panel Right				
12	Right Rear Door	126.6	111	129	140
13	Right Back Panel	114.3	112	115	116

Overall Evaluation :

**B**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p><b>Remarks</b> (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Wheel, Cover - Cap Missing - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes / (R) Rear Wheel, Cover - Cap Missing - Yes / (R) Front Wheel, Cover - Cap Missing - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Partially Missing - Yes / Roof Spoiler, Molding - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Battery - Weak - Yes / Remote Key &amp; Smart entry - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>no warranty booklet/ with jack and tools/ rear hatch cannot be opened/ front passenger window not working from the master switch/ front camera not working/ missing right step board</p>