

General Information

Date & Time: 03, Nov, 2025 10:12

Make	Toyota	Model	Innova
YOM	2019	Odo Meter Reading	154,581
Registration No.	CAQ8453	Chassis No.	PA2CA8EMXK0062321
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	161.3	137	163	184
2	Boot Lid	138.0	141	123	150
3	Roof	193.2	147	149	342/135
4	Left Front Fender	139.0	128	141	148
5	Left Front Door	145.6	145	149	143
6	Center Panel Left				
7	Left Rear Door	151.3	158	149	147
8	Left Back Panel	150.0	158	146	146
9	Right Front Fender	147.3	151	153	138
10	Right Front Door	146.0	138	155	145
11	Center Panel Right				
12	Right Rear Door	146.6	145	149	146
13	Right Back Panel	148.3	128	154	163

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	E	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Large / (R) Rear Trim - Grime - Medium / Rear Seat - Grime - Large / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Rear Trim - Grime - Medium / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Large</p>		<p>Remarks Roof - Repair Traces - Yes / (L) Front Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Roof - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / Roof - Dent - Small / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate/with spare tire/Reverse camera not working/No fog light/No spare key/No warranty booklet/with jack and incomplete tools/audio radio not function/plate light issue/non moving vehicle