

## General Information

Date & Time: 03, Nov, 2025 15:07

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	33,263
<b>Registration No.</b>	NFR2762	<b>Chassis No.</b>	MHFAA1BY2R0025297
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	MPV
<b>Colour</b>	Green		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	114	105	115
2	Boot Lid	103.7	98	109	104
3	Roof	127.2	140	123	118/128
4	Left Front Fender	97.9	83	105	106
5	Left Front Door	119.3	112	121	125
6	Center Panel Left				
7	Left Rear Door	117.0	121	111	119
8	Left Back Panel	115.1	127	120	98
9	Right Front Fender	108.0	118	107	99
10	Right Front Door	113.6	118	113	110
11	Center Panel Right				
12	Right Rear Door	113.6	115	112	114
13	Right Back Panel	111.9	127	91	118

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>  Rear Seat - Grime - Medium / (R) Front Seat - Grime - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Floor Mat - Grime - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small</p>	<p><b>Remarks</b>  Roof - Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b>  Defects not found</p>	<p><b>Remarks</b>  Battery - Weak - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate/with spare tire/with spare key/with jack No tools/with warranty booklet/with reverse camera</p>