

General Information

Date & Time: 25, Oct, 2025 15:55

Make	Isuzu	Model	D-MAX
YOM	2023	Odo Meter Reading	35,660
Registration No.	LAM8275	Chassis No.	MPATTFR87JNT006044
CC	1.9	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	107	110	116
2	Boot Lid	104.6	100	108	106
3	Roof	119.5	116	117	110/135
4	Left Front Fender	275.0	281	274	270
5	Left Front Door	114.0	117	112	113
6	Center Panel Left				
7	Left Rear Door	109.0	115	109	103
8	Left Back Panel	102.6	99	101	108
9	Right Front Fender	115.3	108	118	120
10	Right Front Door	116.6	121	109	120
11	Center Panel Right				
12	Right Rear Door	108.6	101	107	118
13	Right Back Panel	107.3	109	111	102

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / Ceiling - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small</p>	<p>Remarks (R) Front Door, Molding - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Side Gate - Scratch & Dent - Medium / Rear Gate - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Large / Cab Back Panel - Scratch & Dent - Small / Cargo Bed Floor - Scratch - Small / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / Member (Bolted) - Dent - Yes / (R) Rear Wheel, Cover - Cap Missing - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes / (L) Front Wheel, Cover - Cap Missing - Yes / (R) Front Wheel, Cover - Cap Missing - Yes</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate, No warranty booklet and Sparetire and Jack and Tools, No Spare key, no reverse camera, foul smell, worn tires, Scratch headlight and tail light, crack tail light, Plate light issue and tail light busted, headlight issue.</p>